

Requestor information

Requestor name

Aidan Belcher

Phone #

Email

abelcher@icastinc.com

Request details

Date of request

2026-07-02

Location

MH5/Building Sect.

Building

New Ex

Man Hole

5

Equipment/asset/system affected

Crane B

Request description

NewEX/MH5 Crane B: East/West function not working again. Probably need reset.

Type of issue (check all that apply)

- ☐ Automotive
- ☐ Custodial
- ☐ Telehandler/Forklift
- ☐ Tool Repair
- ☐ Other:

- ☐ Grounds
- ☒ Cranes
- ☐ Machine
- ☐ Safety

- ☐ Plumbing
- ☐ Concrete Forms
- ☐ Electrical

Best times for service

ANY

Desired completion date

2026-07-02

Urgency (check one)

- ☐ Low
- ☒ Medium
- ☐ High

For use by maintenance department

Accepted by

Date

Assigned work order #