

Requestor information

Requestor name

Aidan Belcher

Phone #

Email

abelcher@icastinc.com

Request details

Date of request

2026-08-01

Location

MAIN PLANT

Building

WETCAST

Man Hole

1-3

Equipment/asset/system affected

ELECTRIC VIBRATOR

Request description

ELECTRIC VIBRATOR: spring shaft broke inside hose

Type of issue (check all that apply)

- | | | |
|---|----------------------------------|---|
| ☐ Automotive | ☐ Grounds | ☐ Plumbing |
| ☐ Custodial | ☐ Cranes | ☐ Concrete Forms |
| ☐ Telehandler/Forklift | ☐ Machine | ☐ Electrical |
| ☒ Tool Repair | ☐ Safety | |
| ☐ Other: | | |

Best times for service

Desired completion date

Urgency (check one)

- | | |
|-------------------------------------|--------|
| ☐ | Low |
| ☐ | Medium |
| ☒ | High |

☐ Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #

00261