

Requestor information

Requestor name

Aidan Belcher

Phone #

Email

abelcher@icastinc.com

Request details

Date of request

2026-08-22

Location

MAIN PLANT

Building

Man Hole

Equipment/asset/system affected

Gas Backpack Vibrator GHX50

Request description

stopped working, put new hose on, didn't fix it. Think transmission shaft stripped out again

Type of issue (check all that apply)

- ☐ Automotive
☐ Custodial
☐ Telehandler/Forklift
☒ Tool Repair
☐ Other:

- ☐ Grounds
☐ Cranes
☐ Machine
☐ Safety

- ☐ Plumbing
☐ Concrete Forms
☐ Electrical

Best times for service

Urgency (check one)

- ☐ Low
☒ Medium
☐ High

Desired completion date

☐ Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Aidan Belcher

Date

2026-08-24

Assigned work order #

338