

Requestor information

Requestor name

Brallan Hernandez

Phone #

Email

bhernandez@icastinc.com

Request details

Date of request

2026-08-04

Location

mh5

Building

Man Hole

Equipment/asset/system affected

5

Request description

12' core needs immediate repair. it is binding when wrecking out and the lifters on the core are starting to bend inward.

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☒

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☐

Machine

☐

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

Best times for service

morning

Urgency (check one)

☐

Low

☐

Medium

☒

High

Desired completion date

2026-08-07

☐

Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #

Jason Horton

2026-08-06

285