

Requestor information

Requestor name

Phone #

Email

Jason Horton

jhorton@icastinc.com

Request details

Date of request

Location

2026-08-19

Building

Man Hole

Equipment/asset/system affected

hyster 300

Request description

air brake rebuild / brakes working , pedal was rusted sticking /replaced tilt cyl right side

Type of issue (check all that apply)

☐ Automotive

☐ Grounds

☐ Plumbing

☐ Custodial

☐ Cranes

☐ Concrete Forms

☒ Telehandler/Forklift

☐ Machine

☐ Electrical

☐ Tool Repair

☐ Safety

☐ Other:

Best times for service

Urgency (check one)

☐ Low

☒ Medium

☐ High

Desired completion date

Parts

Part Number

Part Name

Quantity

Amount

Parts Total:

For use by maintenance department

Accepted by

Date

Assigned work order #

00319