

## Requestor information

Requestor name

Aidan Belcher

Phone #

Email

abelcher@icastinc.com

## Request details

Date of request

2026-07-23

Location

MAIN PLANT

Building

REBAR HOUSE

Man Hole

FOAM

Equipment/asset/system affected

FOAM CUTTER

## Request description

FOAM CUTTER: Proximity sensor down (staying engaged on right side; will raise up but locks lowering function). Larry is in contact with MegaPlot rep trying to order parts. Awaiting reply.

Part #LMF1-3005NA (Stord)

## Type of issue (check all that apply)

- |                                               |                                             |                                         |
|-----------------------------------------------|---------------------------------------------|-----------------------------------------|
| <input type="checkbox"/> Automotive           | <input type="checkbox"/> Grounds            | <input type="checkbox"/> Plumbing       |
| <input type="checkbox"/> Custodial            | <input type="checkbox"/> Cranes             | <input type="checkbox"/> Concrete Forms |
| <input type="checkbox"/> Telehandler/Forklift | <input checked="" type="checkbox"/> Machine | <input type="checkbox"/> Electrical     |
| <input type="checkbox"/> Tool Repair          | <input type="checkbox"/> Safety             |                                         |
| <input type="checkbox"/> Other:               |                                             |                                         |

Best times for service

Urgency (check one)

- |                                     |        |
|-------------------------------------|--------|
| <input type="checkbox"/>            | Low    |
| <input type="checkbox"/>            | Medium |
| <input checked="" type="checkbox"/> | High   |

Desired completion date

2026-07-27

☐ Return-to-Service (RtS) approval required upon work completion

## For use by maintenance department

Accepted by

Date

Assigned work order #

00239