

Requestor information

Requestor name

Aidan Belcher

Phone #

Email

abelcher@icastinc.com

Request details

Date of request

2026-08-06

Location

MAIN PLANT

Building

OLD

Man Hole

Wetcast

Equipment/asset/system affected

Gas Backpack Vibrator GHX50

Request description

Gas Backpack Vibrator GHX50: The crew had gotten plastic wrap somehow wrapped up into the flywheel. I got that removed. However, in turn they un-tensioned and broke the recoil starter for the second time in less than a week. I have tried to retention the chicken spring but cannot get it to stay tensioned to recoil back. If morning crew could take a look and see if something could be made to work temporarily until a new one comes in, that would be great.

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☒

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☒

Machine

☐

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

Best times for service

ANY

Desired completion date

2026-08-10

Urgency (check one)

☐

Low

☐

Medium

☒

High

☐

Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #

00283