

Requestor information

Requestor name

Jon Fuller

Phone #

Email

jfuller@icastinc.com

Request details

Date of request

2026-08-25

Location

Building

MAIN

Man Hole

Equipment/asset/system affected

OUTSIDE LIGHTS

Request description

Outside lights have been out ~2 months

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☐

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☐

Machine

☒

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

Best times for service

ANY

Urgency (check one)

☐

Low

☐

Medium

☒

High

Desired completion date

2026-08-26

☐

Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #

00340