

Requestor information

Requestor name

Olivia Williams

Phone #

Email

owilliams@icastinc.com

Request details

Date of request

2026-08-27

Location

yard across from main plant

Building

Man Hole

Equipment/asset/system affected

forms

Request description

The asset numbers need to be welded on the 2 new j-bunks. The numbers can be found on the purple ribbon. One is 22710, the other 22711. I have attached photos for reference.

Type of issue (check all that apply)

- | | | |
|---|----------------------------------|--|
| ☐ Automotive | ☐ Grounds | ☐ Plumbing |
| ☐ Custodial | ☐ Cranes | ☒ Concrete Forms |
| ☐ Telehandler/Forklift | ☐ Machine | ☐ Electrical |
| ☐ Tool Repair | ☐ Safety | |
| ☐ Other: | | |

Best times for service

Urgency (check one)

- | | |
|-------------------------------------|--------|
| ☐ | Low |
| ☒ | Medium |
| ☐ | High |

Desired completion date

2026-09-01

☐ Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #

00348