

Requestor information

Requestor name

Jason Horton

Phone #

Email

jhorton@icastinc.com

Request details

Date of request

2026-06-23

Location

wetcast mixer 2

Building

wetcast

Man Hole

Equipment/asset/system affected

Mixer 2

Request description

Mixer paddle checks adjust paddle distance from bottom 1/4" clearance

Type of issue (check all that apply)

- ☐ Automotive
- ☐ Custodial
- ☐ Telehandler/Forklift
- ☐ Tool Repair
- ☐ Other:

- ☐ Grounds
- ☐ Cranes
- ☒ Machine
- ☐ Safety

- ☐ Plumbing
- ☐ Concrete Forms
- ☐ Electrical

Best times for service

Desired completion date

Urgency (check one)

- ☐ Low
- ☒ Medium
- ☐ High

For use by maintenance department

Accepted by

Date

Assigned work order #

00113