

Requestor information

Requestor name

Jon Fuller

Phone #

2708201966

Email

jfuller@icastinc.com

Request details

Date of request

2026-06-01

Location

SYMONS

Building

Man Hole

Equipment/asset/system affected

OIL SPRAYER CART

Request description

Not spraying a fine mist as required

Type of issue (check all that apply)

Automotive

Custodial

Telehandler/Forklift

Tool Repair

Other:

Grounds

Cranes

Machine

Safety

Plumbing

Concrete Forms

Electrical

Best times for service

asap

Desired completion date

2026-06-01

Urgency (check one)

Low

Medium

High

For use by maintenance department

Accepted by

Date

Assigned work order #

00005