

## Requestor information

Requestor name

Jon Fuller

Phone #

2708201966

Email

jfuller@icastinc.com

## Request details

Date of request

2026-06-01

Location

SYMONS

Building

Man Hole

Equipment/asset/system affected

CRANE #1

## Request description

Totally unresponsive

### Type of issue (check all that apply)

- |   |  |   |
|---|--|---|
| <input type="checkbox"/> Automotive           | <input type="checkbox"/> Grounds           | <input type="checkbox"/> Plumbing       |
| <input type="checkbox"/> Custodial            | <input checked="" type="checkbox"/> Cranes | <input type="checkbox"/> Concrete Forms |
| <input type="checkbox"/> Telehandler/Forklift | <input type="checkbox"/> Machine           | <input type="checkbox"/> Electrical     |
| <input type="checkbox"/> Tool Repair          | <input type="checkbox"/> Safety            |   |
| <input type="checkbox"/> Other:               |  |   |

### Best times for service

asap

### Desired completion date

2026-06-01

### Urgency (check one)

- |                                     |        |
|-------------------------------------|--------|
| <input type="checkbox"/>            | Low    |
| <input type="checkbox"/>            | Medium |
| <input checked="" type="checkbox"/> | High   |

## For use by maintenance department

Accepted by

Date

Assigned work order #

00006