

## Requestor information

Requestor name

Jon Fuller

Phone #

2708201966

Email

jfuller@icastinc.com

## Request details

Date of request

2026-06-08

Location

SYMONS

Building

OLD

Man Hole

Equipment/asset/system affected

OIL SPRAYER CART

## Request description

Clogged filter? Doesn't spray.

## Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☒

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☐

Machine

☐

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

## Best times for service

asap

## Urgency (check one)

☐

Low

☒

Medium

☐

High

## Desired completion date

2026-06-09

## For use by maintenance department

Accepted by

Zach Stevens

Date

2026-06-19

Assigned work order #

109