

Requestor information

Requestor name

Chad Jarvis

Phone #

2709773522

Email

chad@icastinc.com

Request details

Date of request

2026-06-12

Location

Wet Cast Silo Area

Building

Man Hole

Equipment/asset/system affected

Bucket Washout Area

Request description

Area behind silos has been scooped out and is holding water creating an unsafe condition for silo loading

Type of issue (check all that apply)

☐

Automotive

☒

Grounds

☐

Plumbing

☐

Custodial

☐

Cranes

☐

Concrete Forms

☐

Telehandler/Forklift

☐

Machine

☐

Electrical

☐

Tool Repair

☒

Safety

☐

Other:

Best times for service

After silos are full

Urgency (check one)

☐

Low

☒

Medium

☐

High

Desired completion date

2026-06-16

For use by maintenance department

Accepted by

Date

Assigned work order #

00043