

Requestor information

Requestor name

Jon Fuller

Phone #

Email

jfuller@icastinc.com

Request details

Date of request

2026-06-15

Location

Building

New

Man Hole

12'

Equipment/asset/system affected

Core

Request description

Inside support bent. Leaves a gap between core and pallet.

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☐

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☐

Machine

☐

Safety

☐

Plumbing

☒

Concrete Forms

☐

Electrical

Best times for service

asap

Urgency (check one)

☐

Low

☐

Medium

☒

High

Desired completion date

2026-06-15

For use by maintenance department

Accepted by

Zach Stevens

Date

2026-06-15

Assigned work order #

54