

Requestor information

Requestor name

Phone #

Email

Brallan Hernandez

bhernandez@icastinc.com

Request details

Date of request

Location

2026-06-18

Outside

Building

Man Hole

Equipment/asset/system affected

4

Request description

weld chain back onto door of TDOT headwall form. Weld bottle jack onto FES form.

Type of issue (check all that apply)

☐

Automotive

☐

Grounds

☐

Plumbing

☐

Custodial

☐

Cranes

☐

Concrete Forms

☐

Telehandler/Forklift

☐

Machine

☐

Electrical

☒

Tool Repair

☐

Safety

☐

Other:

Best times for service

Urgency (check one)

☐

Low

☒

Medium

☐

High

Desired completion date

2026-06-18

For use by maintenance department

Accepted by

Date

Assigned work order #

00098