

Requestor information

Requestor name

John Hightower

Phone #

(850)557-0009

Email

jhightower@icastinc.com

Request details

Date of request

2026-06-18

Location

Pipe Plant

Building

Pipe Plant

Man Hole

Equipment/asset/system affected

38x60 Wet Cast Form

Request description

Need spacer blocks installed on the jacket of the 38x60 to keep the core perfectly aligned with the jacket to prevent thick and thin issues. This has been requested verbally for sometime and needs to get done.

Type of issue (check all that apply)

- | | | |
|---|----------------------------------|--|
| ☐ Automotive | ☐ Grounds | ☐ Plumbing |
| ☐ Custodial | ☐ Cranes | ☒ Concrete Forms |
| ☐ Telehandler/Forklift | ☐ Machine | ☐ Electrical |
| ☐ Tool Repair | ☐ Safety | |
| ☐ Other: | | |

Best times for service

First thing AM after product is stripped

Urgency (check one)

- | | |
|-------------------------------------|--------|
| ☐ | Low |
| ☒ | Medium |
| ☐ | High |

Desired completion date

2026-06-19

For use by maintenance department

Accepted by

Zach Stevens

Date

2026-06-19

Assigned work order #

107