

Requestor information

Requestor name

Jon Fuller

Phone #

Email

jfuller@icastinc.com

Request details

Date of request

2026-07-01

Location

CORE BUILDING

Building

CORING

Man Hole

N/A

Equipment/asset/system affected

VIBRATOR

Request description

Loose wires on the panel wall vibrator.

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☒

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☐

Machine

☒

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

Best times for service

ANY

Desired completion date

2026-07-01

Urgency (check one)

☐

Low

☐

Medium

☒

High

For use by maintenance department

Accepted by

Aidan Belcher

Date

2026-07-01

Assigned work order #

168