

Requestor information

Requestor name

Aidan Belcher

Phone #

Email

abelcher@icastinc.com

Request details

Date of request

2026-07-07

Location

Hawkeye

Building

New Ex

Man Hole

Pipe

Equipment/asset/system affected

Sicoma Drycast Mixer

Request description

Dry cast mixer overheating, check oil, top off and grease.

Type of issue (check all that apply)

- ☐ Automotive
- ☐ Custodial
- ☐ Telehandler/Forklift
- ☐ Tool Repair
- ☐ Other:

- ☐ Grounds
- ☐ Cranes
- ☒ Machine
- ☐ Safety

- ☐ Plumbing
- ☐ Concrete Forms
- ☐ Electrical

Best times for service

Evening

Desired completion date

2026-07-08

Urgency (check one)

- ☐ Low
- ☐ Medium
- ☒ High

For use by maintenance department

Accepted by

Aidan Belcher

Date

2026-07-08

Assigned work order #

188