

Requestor information

Requestor name

Jon Fuller

Phone #

2708201966

Email

jfuller@icastinc.com

Request details

Date of request

2026-07-15

Location

WET CAST GRIZZLY PIT

Building

N/A

Man Hole

N/A

Equipment/asset/system affected

GRIZZLY PIT

Request description

Aggregate is falling of the belt and piling up at the back of the belt. Pour crew says this is daily to the point that it rubs the belt.

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☐

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☒

Machine

☐

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

Best times for service

Urgency (check one)

☐

Low

☐

Medium

☒

High

Desired completion date

2026-07-16

☐

Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #

00214