

Requestor information

Requestor name

Aidan Belcher

Phone #

Email

abelcher@icastinc.com

Request details

Date of request

2026-07-21

Location

MAIN PLANT

Building

Dry Cast

Man Hole

Besser

Equipment/asset/system affected

Cat GP55N1 Forklift

Request description

Cat GP55N1 Forklift horn stuck on

Type of issue (check all that apply)

- ☐ Automotive
- ☐ Custodial
- ☐ Telehandler/Forklift
- ☐ Tool Repair
- ☒ Other: Forklift

- ☐ Grounds
- ☐ Cranes
- ☒ Machine
- ☐ Safety

- ☐ Plumbing
- ☐ Concrete Forms
- ☐ Electrical

Best times for service

ASAP

Desired completion date

2026-07-21

Urgency (check one)

- ☐ Low
- ☐ Medium
- ☒ High

☐ Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Aidan Belcher

Date

2026-07-21

Assigned work order #

224