

Requestor information

Requestor name

Jon Fuller

Phone #

2708201966

Email

jfuller@icastinc.com

Request details

Date of request

2026-07-23

Location

MH2

Building

OLD NEW

Man Hole

MH2

Equipment/asset/system affected

BOX FORMS

Request description

I don't know whether they're asking for new bolts/nuts for the box form trunnions or for them to be tightened.

-New nuts and bolts.

Type of issue (check all that apply)

- | | | |
|---|----------------------------------|--|
| ☐ Automotive | ☐ Grounds | ☐ Plumbing |
| ☐ Custodial | ☐ Cranes | ☒ Concrete Forms |
| ☐ Telehandler/Forklift | ☐ Machine | ☐ Electrical |
| ☐ Tool Repair | ☐ Safety | |
| ☐ Other: | | |

Best times for service

ANY

Urgency (check one)

- | | |
|-------------------------------------|--------|
| ☐ | Low |
| ☒ | Medium |
| ☐ | High |

Desired completion date

2026-07-24

☐ Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #