

Requestor information

Requestor name

Jon Fuller

Phone #

2708201966

Email

jfuller@icastinc.com

Request details

Date of request

2026-07-30

Location

Building

CORING

Man Hole

Equipment/asset/system affected

CORE TABLE

Request description

Turntables are leaking hydraulic oil

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☐

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☒

Machine

☐

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

Best times for service

AFTER 5

Desired completion date

2026-08-05

Urgency (check one)

☐

Low

☒

Medium

☐

High

☐

Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #

00252