

Requestor information

Requestor name

Olivia Williams

Phone #

Email

owilliams@icastinc.com

Request details

Date of request

2026-08-05

Location

symons

Building

Man Hole

Equipment/asset/system affected

air hose

Request description

The air hose reel has stopped winding the air hose. Currently winding the hose up manually.

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☒

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☐

Machine

☐

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

Best times for service

Urgency (check one)

☒

Low

☐

Medium

☐

High

Desired completion date

2026-08-26

☐

Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #

Aidan Belcher

2026-08-05

282