

Requestor information

Requestor name

Phone #

Email

Brallan Hernandez

bhernandez@icastinc.com

Request details

Date of request

Location

2026-08-06

OUT BY MH4

Building

Man Hole

Equipment/asset/system affected

Request description

The 9' manhole jacket needs the handle repair. from the looks of it was bent and damaged by a machine.

Type of issue (check all that apply)

- | | | |
|---|----------------------------------|---|
| ☐ Automotive | ☐ Grounds | ☐ Plumbing |
| ☐ Custodial | ☐ Cranes | ☐ Concrete Forms |
| ☐ Telehandler/Forklift | ☐ Machine | ☐ Electrical |
| ☒ Tool Repair | ☐ Safety | |
| ☐ Other: | | |

Best times for service

anytime

Urgency (check one)

- | | |
|-------------------------------------|--------|
| ☐ | Low |
| ☐ | Medium |
| ☒ | High |

Desired completion date

2026-08-11

☐ Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #

00284