

Requestor information

Requestor name

Phone #

Email

Jon Fuller

jfuller@icastinc.com

Request details

Date of request

Location

2026-08-17

MH2

Building

Man Hole

Equipment/asset/system affected

MH2

B&N REBAR CUTTER

Request description

Needs blade housing (ordered?) and replaced.

Type of issue (check all that apply)

☐ Automotive

☐ Grounds

☐ Plumbing

☐ Custodial

☐ Cranes

☐ Concrete Forms

☐ Telehandler/Forklift

☐ Machine

☐ Electrical

☒ Tool Repair

☐ Safety

☐ Other:

Best times for service

ANY

Urgency (check one)

☐ Low

☐ Medium

☒ High

Desired completion date

2026-08-24

☒ Return-to-Service (RtS) approval required upon work completion

Approving departments: Maintenance, Operations, Safety

For use by maintenance department

Accepted by

Date

Assigned work order #

00317