

Requestor information

Requestor name

Jason Horton

Phone #

Email

jhorton@icastinc.com

Request details

Date of request

2026-08-22

Location

wetcast mixer 2

Building

wetcast

Man Hole

Equipment/asset/system affected

Mixer 2

Request description

Mixer paddle checks adjust paddle distance from bottom 1/4" clearance

Type of issue (check all that apply)

- | | | |
|---|---|---|
| ☐ Automotive | ☐ Grounds | ☐ Plumbing |
| ☐ Custodial | ☐ Cranes | ☐ Concrete Forms |
| ☐ Telehandler/Forklift | ☒ Machine | ☐ Electrical |
| ☐ Tool Repair | ☐ Safety | |
| ☐ Other: | | |

Best times for service

Urgency (check one)

- | | |
|-------------------------------------|--------|
| ☐ | Low |
| ☒ | Medium |
| ☐ | High |

Desired completion date

☐ Return-to-Service (RtS) approval required upon work completion

For use by maintenance department

Accepted by

Date

Assigned work order #

00330