

Mobile Machine WORK ORDER

Machine	Order Number
John Deere 524 Loader	00170
Asset #	Order Received By

VIN	Make and Model
1DW524PATMLZ10780	John Deere 524
Odometer Reading	Motor #
1873.6hr	
License # and State	

☐	Lubricate	☐	Wiper Replacement	☐	Air Filter Replacement
☐	Change Oil	☐	Boom Repair	☐	Spark Plug Replacement
☐	Transmission Service	☐	Fuel System	☐	Exhaust System Check
☐	Battery Replacement / Check	☐	Tire Replacement	☐	Electronics
☐	Differential Service	☐	Brake Inspection / Replacement	☐	Suspension and Steering Check
☐	Flat Tire Repair	☐	Coolant System Flush	☐	Hydraulic repair / fill

Labor Description	Time
Overheating-washed and blown out radiator and other coolers. Ready to test for overheating on 1st Shift.	

Labor Total:

[illegible]

Work Order Compiled By	Date
Work Authorized By	Authorization Date