

ICAST

Mobile Machine WORK ORDER

Machine Information

Machine	Order Number	
JOHN DEERE TRACTOR		
Asset #	Order Received By	
40007		
Order Date & Time	Date Promised	Date Delivered
2026-06-17T15:53		

Vehicle Information

VIN	Make and Model
LV5200E620939	Caterpillar
Odometer Reading	Motor #
License # and State	

Service Type

☒ Lubricate
☒ Change Oil
☒ Transmission Service
☐ Battery Replacement / Check
☐ Differential Service
☐ Flat Tire Repair

☐ Wiper Replacement
☐ Boom Repair
☐ Fuel System
☐ Tire Replacement
☐ Brake Inspection / Replacement
☐ Coolant System Flush

☒ Air Filter Replacement
☐ Spark Plug Replacement
☐ Exhaust System Check
☐ Electronics
☒ Suspension and Steering Check
☒ Hydraulic repair / fill

Labor DescriptionTime

PM MACHINE CAPTURE FILTERS TO FORM

Time: Labor Total:

Parts

Part Number	Part Name	Quantity	Amount
3532	FUEL		
1740	TRANS	1	
1243	oil filter	1	
6489	air filter	1	
546490	air filter		

☐ Awaiting Approval on parts ☐ Parts Ordered Parts Total:

Authorization

Work Order Compiled By	Date
Work Authorized By	Authorization Date