

ICAST

Mobile Machine WORK ORDER

Machine Information

Machine	Order Number	
HYSTER 120 forklift		
Asset #	Order Received By	
40006		
Order Date & Time	Date Promised	Date Delivered
2026-06-17T16:30		

Vehicle Information

VIN	Make and Model
P005V02523G	Caterpillar
Odometer Reading	Motor #
License # and State	

Service Type

☒ Lubricate
☒ Change Oil
☐ Transmission Service
☐ Battery Replacement / Check
☐ Differential Service
☐ Flat Tire Repair

☐ Wiper Replacement
☐ Boom Repair
☐ Fuel System
☐ Tire Replacement
☐ Brake Inspection / Replacement
☐ Coolant System Flush

☒ Air Filter Replacement
☐ Spark Plug Replacement
☐ Exhaust System Check
☐ Electronics
☐ Suspension and Steering Check
☒ Hydraulic repair / fill

Labor Description

PM capture filters in parts

Time:

Labor Total:

Parts

Part Number	Part Name	Quantity	Amount
	FUEL		
	TRANS	1	
1036	oil filter	1	
P616742	air filter	1	
	air filter		

☐ Awaiting Approval on parts

☐ Parts Ordered

Parts Total:

Authorization

Work Order Compiled By	Date
Work Authorized By	Authorization Date