

ICAST

Mobile Machine WORK ORDER

Machine Information

Machine

Kubota RTV900

Order Number

00085

Asset #

40050

Order Received By

Order Date & Time

2026-06-17T18:26

Date Promised

Date Delivered

Vehicle Information

VIN

35631

Make and Model

Odometer Reading

Motor #

License # and State

Service Type

☒

Lubricate

☒

Change Oil

☐

Transmission Service

☐

Battery Replacement / Check☐☐

☐

Wiper Replacement☐☐☐☐☐

☒

Air Filter Replacement☐☐☐☐☐

Labor Description

PM

Time

Time:

Labor Total:

Parts

Part Number

1365

Part Name

OIL FILTER

Quantity

1

Amount

500428

AIR FILTER

1

☐ Awaiting Approval on parts

☐ Parts Ordered

Parts Total:

Authorization

Work Order Compiled By

Jason Horton

Date

2026-06-17

Work Authorized By

Authorization Date