

ICAST

Mobile Machine WORK ORDER

Machine Information

Machine

09 forklift

Asset #

Order Number

00249

Order Received By

Order Date & Time

2026-07-27T21:42

Date Promised

Date Delivered

Vehicle Information

VIN

Make and Model

Odometer Reading

Motor #

License # and State

Service Type

☐ Lubricate

☐ Change Oil

☐ Transmission Service

☐ Battery Replacement / Check

☐ Differential Service

☐ Flat Tire Repair

☐ Wiper Replacement

☐ Boom Repair

☐ Fuel System

☐ Tire Replacement

☐ Brake Inspection / Replacement

☐ Coolant System Flush

☐ Air Filter Replacement

☐ Spark Plug Replacement

☐ Exhaust System Check

☐ Electronics

☐ Suspension and Steering Check

☒ Hydraulic repair / fill

Labor Description

Mass tilt cylinder left-hand side with sitting on machine seal is blown

Time:

Labor Total:

Parts

Part Number

Part Name

Quantity

Amount

Parts Total:

Authorization

Work Order Compiled By

Date

Work Authorized By

Authorization Date