

Requestor information

Requestor name

Jason Horton

Phone #

Email

jhorton@icastinc.com

Request details

Date of request

2026-06-17

Location

Building

pipe

Man Hole

pipe

Equipment/asset/system affected

besser

Attached repair / operator manual

BiDi-Service-and-Lubrication-Chart.pdf

Request description

PM and add gear box and conveyor belt

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☐

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☒

Machine

☐

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

Best times for service

Urgency (check one)

☐

Low

☒

Medium

☐

High

Desired completion date

Parts

Part Number

Part Name

Quantity

Amount

☐

Awaiting Approval on parts

☐

Parts Ordered

Parts Total:

For use by maintenance department

Accepted by

Jason Horton

Date

2026-06-18

Assigned work order #

101