

Requestor information

Requestor name

Jason Horton

Phone #

Email

jhorton@icastinc.com

Request details

Date of request

2026-07-10

Location

Building

wetcast

Man Hole

1

Equipment/asset/system affected

Crane #2

Attached repair / operator manual

Crane_PM_and_Daily_Checklist.docx

Request description

Pm per schedule , please mark date on sheet so we will know 30day,90,180 annual

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☐

Tool Repair

☐

Other:

☐

Grounds

☒

Cranes

☐

Machine

☐

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

Best times for service

Urgency (check one)

☐

Low

☒

Medium

☐

High

Desired completion date

Parts

Part Number

Part Name

Quantity

Amount

Parts Total:

For use by maintenance department

Accepted by

Aidan Belcher

Date

2026-07-10

Assigned work order #

203