

Requestor information

Requestor name

Jason Horton

Phone #

Email

jhorton@icastinc.com

Request details

Date of request

2026-06-24

Location

Rebar

Building

Man Hole

Equipment/asset/system affected

Rebar bender

Request description

PM rebar Bender grease check wiring and hyd hoses and sivals

Type of issue (check all that apply)

☐

Automotive

☐

Custodial

☐

Telehandler/Forklift

☐

Tool Repair

☐

Other:

☐

Grounds

☐

Cranes

☒

Machine

☒

Safety

☐

Plumbing

☐

Concrete Forms

☐

Electrical

Best times for service

Urgency (check one)

☐

Low

☒

Medium

☐

High

Desired completion date

Parts

Part Number

Part Name

Quantity

Amount

Parts Total:

For use by maintenance department

Accepted by

Aidan Belcher

Date

2026-08-04

Assigned work order #

271