

Requestor information

Requestor name

Olivia Williams

Phone #

Email

owilliams@icastinc.com

Request details

Date of request

2026-08-24

Location

parcel building

Building

parcel building

Man Hole

Equipment/asset/system affected

Request description

Please assemble the cart located in the parcel building for Augustino (Fullers repair/installation worker). I set this as high priority due to ergonomical reasons based off of his current setup. I have attached a photo of the box that the cart is in.

Type of Safety issue (check all that apply)

☐

Slip/Trip/Fall

☐

Lighting

☐

Mobile equipment

☐

Tool/Cords

☐

Other:

☐

Isleway or Egress

☐

Near Miss

☐

Machine

☐

Building

☒

General Safety

☐

Concrete Forms

☐

Electrical

Best times for service

Urgency (check one)

☐

Low

☐

Medium

☒

High

Desired completion date

2026-08-26

For use by Safety department

Accepted by

Date

Assigned work order #

00337